

Faucet Repairs

FR001 - Moen Single Lever Kitchen Repair (Complete)

Total Hours	1.00	Technician's Compensation			
		Material	Labor	Bonus	Total
Standard Rate	\$201.90	\$3.44	\$21.00	\$10.10	\$34.53
Premium Rate	\$236.50	\$3.44	\$31.50	\$11.82	\$46.76
Service Agreement	\$181.71	\$3.44	\$21.00	\$9.09	\$33.52

Qty	Part #	Description
1	PRM-010	Springflow Chrome Airator
1	FCM-410	Moen Spout O-Ring Kit
1	PRC014	Grease Per Repair
1	FCM-385	Moen Magnum Cartridge

Inspect condition of faucet, if spout and body is in good shape continue with repair, if not recommend replacement. close water, remove handle, cartridge, spout. install new cartridge, hose diverter, and spout o-rings. re-install handle, turn on water test.

FR005 - Moen Single Lever Faucet Repair (Kit/Lav)

Total Hours	1.00	Technician's Compensation			
		Material	Labor	Bonus	Total
Standard Rate	\$188.63	\$2.50	\$21.00	\$9.43	\$32.93
Premium Rate	\$222.56	\$2.50	\$31.50	\$11.13	\$45.13
Service Agreement	\$169.77	\$2.50	\$21.00	\$8.49	\$31.99

Qty	Part #	Description
1	PRC014	Grease Per Repair
1	FCM-385	Moen Magnum Cartridge

FR010 - Moen 2 Handle Faucet Repair (Kit/Lav)

Total Hours	1.00	Technician's Compensation			
		Material	Labor	Bonus	Total
Standard Rate	\$191.49	\$2.70	\$21.00	\$9.57	\$33.27
Premium Rate	\$225.57	\$2.70	\$31.50	\$11.28	\$45.48
Service Agreement	\$172.34	\$2.70	\$21.00	\$8.62	\$32.32

Qty	Part #	Description
1	PRC014	Grease Per Repair
2	FCM-390	Moen 2 Hndl & Widespread Replacement Cartridge

FR015 - Moen Kitchen Faucet Diverter Replacement

Total Hours	0.50	Technician's Compensation			
		Material	Labor	Bonus	Total
Standard Rate	\$103.43	\$1.66	\$10.50	\$5.17	\$17.33
Premium Rate	\$120.85	\$1.66	\$15.75	\$6.04	\$23.45
Service Agreement	\$93.08	\$1.66	\$10.50	\$4.65	\$16.81

Qty	Part #	Description
1	FCM-425	KITCHEN FAUCET SPRAY HOSE DIVERTER ASSEMBLY

FR017 - Moen Kitchen Faucet Spout Replacement (Legend)

Total Hours	0.50	Technician's Compensation			
		Material	Labor	Bonus	Total
Standard Rate	\$197.02	\$8.28	\$10.50	\$9.85	\$28.63
Premium Rate	\$219.13	\$8.28	\$15.75	\$10.96	\$34.99
Service Agreement	\$177.32	\$8.28	\$10.50	\$8.87	\$27.65

Qty	Part #	Description
1	FCM-410	Moen Spout O-Ring Kit
1	FCM-408	Moen Kitchen Spout Legend 99719

Inspect faucet quote client price on repair and replacement in writing on invoice. after approval, close water, remove handle, remove spout and install new spout and o-ring kit. test check for leaks.

Your Company Name Here